

CLEAN HARBORS ENVIRONMENTAL SERVICES, INC.
LAND DISPOSAL RESTRICTION FORM LDR-1

MANIFEST NO

006052598 FLE

THE HAZARDOUS WASTES IDENTIFIED ON THE HAZARDOUS WASTE MANIFEST IDENTIFIED ABOVE AND BEARING THE EPA HAZARDOUS WASTE CODES LISTED BELOW ARE RESTRICTED WASTES WHICH ARE PROHIBITED FROM LAND DISPOSAL WITHOUT FURTHER TREATMENT UNDER THE LAND DISPOSAL RESTRICTIONS, 40 CFR PART 268.7 (a)(2), AND RCRA SECTION 3004(D). IN ACCORDANCE WITH 40 CFR 268.7(a), THE EPA WASTE CODE, WASTE SUBCATEGORY, AND TREATABILITY GROUPS, AS APPLICABLE, ARE INCLUDED BELOW.

INSTRUCTIONS - COMPLETE ALL SECTIONS. REFER TO PAGE 3 OF THIS FORM FOR KEY TERMS/DEFINITIONS.

- Column 1 - Line Item:** Enter the manifest line item number (e.g., 11a) that corresponds to the waste code(s).
Column 2 - Waste Codes/Subcategory: Check off all applicable waste codes. For D001 through D043, also check applicable subcategory; for F001 through F005, check applicable constituents.
Column 3 - Wastewater/Non-wastewater: Check off "WW" for wastewater and "Non-WW" for non-wastewaters.
Column 4 - LDR Handling Code: Circle the appropriate handling code, as follows:
- 1 = The waste is a characteristic hazardous waste D001, D002, D003, D004-D011, or D018-43 which is intended for treatment/disposal in a CWA system, CWA-equivalent system, or Class I SDWA system. Underlying Hazardous Constituents (UHC's) are NOT required to be identified.
 - 1A = The waste is a characteristic hazardous waste D001 High TOC Ignitable Liquids Subcategory (i.e., greater than or equal to 10% TOC). Pursuant to 40 CFR 268.4Q, the waste must be treated using organic recovery (RORGs) or combustion (CMBST) technology. UHC's are NOT required to be identified.
 - 2 = The waste is a characteristic hazardous waste D001 (other than High TOC Ignitable Liquids), D002, D003 Explosive, Water Reactive or Other Reactive subcategory, D004-D011, D012-17 non-wastewater, or D018-43 which is intended for treatment/disposal in a non-CWA system, non-CWA-equivalent system, or non-Class I SDWA system located in the United States. All UHC's which are reasonably expected to be present must be identified, except for D001 waste that is intended to be treated using organic recovery (RORGs) or combustion (CMBST) technologies. Identify UHC's by completing Sections I and IV of CHI Form LDR-1 Addendum and attach completed Addendum to this form.
 - 3 = The waste is a characteristic (i.e., D-code) or listed (i.e., F-, K-, U- or P-code) hazardous waste which is intended for export and treatment/disposal at a facility located outside the United States. LDR treatment standards do not apply to hazardous waste treated/disposed in a foreign country, and per USEPA guidance, the identification of UHC's (if applicable) is not required for hazardous waste that is intended to be exported. Note however that if the exported waste is subsequently returned for treatment/disposal in the United States, all applicable LDR regulations would apply and a revised LDR notification would be required.
 - 4 = The waste meets the definition of hazardous debris pursuant to 40 CFR 268.2(h) and is intended for treatment/ disposal in compliance with the alternate debris treatment technologies of 40 CFR 268.45. In accordance with the requirements of 40 CFR 268.7(a)(2): the contaminants subject to treatment (CSTT's) must be identified as part of this notification. Identify CSTT's by completing Section III and IV of the CHI Form LDR-1 Addendum and attach completed Addendum to this form. These constituents are being treated to comply with 40 CFR 268.45.
 - 5 = The waste is a characteristic waste D003 Reactive Sulfide, Reactive Cyanide, or Unexploded Ordnance subcategory, a characteristic waste D012- 17 wastewater, or a listed (i.e., F-, K-, U-, or P-code) hazardous waste. UHC's are NOT required to be identified.
 - 6 = The waste is a lab pack that is intended for incineration using the alternative lab pack treatment standard under 40 CFR 268.42(c). UHC's are NOT required to be identified; however, the generator must complete and attach the lab pack certification statement on CHI Form LDR-LP. Note that in accordance with 40 CFR Part 268 Appendix IV, lab packs which contain waste codes D008, F019, K003, K004, K005, K008, K062, K071, K100, K108, P010, P011, P012, P078, P078, U134, and U151 are not eligible for alternative lab pack treatment standard.

NOTE: IF THE WASTE IS A SOIL CONTAMINATED WITH A LISTED OR CHARACTERISTIC WASTE AND THE GENERATOR WANTS TO USE THE ALTERNATE TREATMENT STANDARD FOR SOILS, CONTACT CORPORATE COMPLIANCE FOR THE APPROPRIATE LDR NOTIFICATION FORM.

SECTION I. CHARACTERISTIC WASTES D001 THROUGH D043

COLUMN 1: LINE ITEM SEE MANIFEST	COLUMN 2: WASTE CODE / SUBCATEGORY	COLUMN 3: WASTEWATER/ NON-WASTEWATER	COLUMN 4: HANDLING CODE
1	<input type="checkbox"/> D001 Ignitables, except High TOC subcategory	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	2 3 4 6
	<input checked="" type="checkbox"/> D001 High TOC Ignitable Liquids Subcategory (Greater than or equal to 10% TOC)	<input checked="" type="checkbox"/> Non-WW only	1A 3 6
	<input type="checkbox"/> D002 Corrosives	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 2 3 4 6
	<input type="checkbox"/> D003		
	<input type="checkbox"/> Reactive Sulfide, per 261.23 (a)(5)	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 3 4 5 6
	<input type="checkbox"/> Reactive Cyanide, per 261.23(a)(5)	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 3 4 5 6
	<input type="checkbox"/> Explosive, per 261.23(a)(6), (7) & (8)	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 2 3 4 6
	<input type="checkbox"/> Water Reactive, per 261.23(a)(2), (3) & (4)	<input type="checkbox"/> Non-WW only	1 2 3 4 6
	<input type="checkbox"/> Other Reactive, per 261.23(a)(1)	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 2 3 4 6
	<input type="checkbox"/> Unexploded Ordnance, Emergency Response	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 3 4 5 6
	<input type="checkbox"/> D004 Arsenic	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 3 4 5 6
	<input type="checkbox"/> D005 Barium	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 3 4 5 6
	<input type="checkbox"/> D006		
	<input type="checkbox"/> Cadmium	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 2 3 4 6
	<input type="checkbox"/> Cadmium Containing Batteries	<input type="checkbox"/> Non-WW only	2 3 6
	<input type="checkbox"/> D007 Chromium	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 2 3 4 6
	<input type="checkbox"/> D008		
	<input type="checkbox"/> Lead	<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	1 2 3 4 6
	<input type="checkbox"/> Lead Acid Batteries	<input type="checkbox"/> Non-WW only	2 3 6

SECTION III. CALIFORNIA LIST WASTES

COLUMN 1: LINE ITEM SEE MANIFEST	COLUMN 2: WASTE CODE / SUBCATEGORY	COLUMN 3: WASTEWATER/ NON-WASTEWATER	COLUMN 4: HANDLING CODE					
_____	Hazardous waste containing one or more of the following [] WW [] Non-WW California List constituents:		1	2	3	4	5	6
	[] ALL CALIFORNIA LIST CONSTITUENTS							
	[] Liquids with nickel greater than or equal to 134 mg/l							
	[] Liquids with thallium greater than or equal to 130 mg/l							
	[] Liquids with PCB's > or = 50 ppm							
	[] Waste containing HOC's > or = 1,000 mg/kg							

SECTION IV. OTHER LISTED WASTES (F006-12, F019-F028, F037-38, F039, K-, U-, AND P-CODES)

COLUMN 1: LINE ITEM SEE MANIFEST	COLUMN 2: WASTE CODE / SUBCATEGORY	COLUMN 3: WASTEWATER/ NON-WASTEWATER	COLUMN 4: HANDLING CODE					
_____	_____	[] WW [] Non-WW	3	4	5	6		
_____	_____	[] WW [] Non-WW	3	4	5	6		
_____	_____	[] WW [] Non-WW	3	4	5	6		
_____	_____	[] WW [] Non-WW	3	4	5	6		
_____	_____	[] WW [] Non-WW	3	4	5	6		

[] CHECK HERE IF ADDITIONAL LISTED WASTE CODES ARE PRESENT. COMPLETE AND ATTACH LDR-1 CONTINUATION SHEET.

[] CHECK HERE IF WASTE CODE F039 (MULTISOURCE LEACHATE) IS PRESENT. IDENTIFY F039 CONSTITUENTS BY COMPLETING SECTIONS II AND IV OF CHI FORM LDR-1 ADDENDUM AND ATTACH COMPLETED ADDENDUM TO THIS FORM.

SECTION V. CONTACT NAME AND DATE

Print Name: Daniel J. [Signature] Date: 1-9-14

KEY TERMS/DEFINITIONS

CLASS I SDWA SYSTEM means a Class I deep well facility regulated under the Safe Drinking Water Act (SDWA).

CWA SYSTEM means a centralized wastewater treatment facility discharging under a Clean Water Act (CWA) permit. For example, a CWA facility would treat organic or inorganic aqueous wastes and discharge the treated effluent to the local sewer system. Examples of CWA treatment systems owned and operated by Clean Harbors include the wastewater treatment operations at Baltimore (including the CES system), Bristol, Chicago, Cincinnati and Cleveland.

CWA-EQUIVALENT SYSTEM means a "zero discharge system" that engages in "CWA-equivalent" treatment before land disposal. Zero-discharge facilities treat hazardous wastes using "CWA-equivalent" treatment methods, but do not discharge the treatment effluent to a sewer or water body (e.g., spray irrigation land farm). "CWA-equivalent" treatment methods means biological treatment for organics, alkaline chlorination, or ferrous sulfate precipitation for cyanide, precipitation/ sedimentation for metals, reduction of hexavalent chromium, or other treatment technology that can be demonstrated to perform equally or greater than these technologies.

HIGH TOC IGNITABLE LIQUIDS SUBCATEGORY means an ignitable liquid hazardous waste (waste code D001) which contains greater than or equal to 10% total organic carbon (TOC). Pursuant to 40 CFR 268.40, such wastes must be treated using organic recovery (RORGs) or combustion (CMBST) technology. Examples of RORGs technologies include the CES unit at Clean Harbors of Baltimore. Examples of CMBST technologies include hazardous waste fuel blending and subsequent reuse at a cement kiln, or destruction at a RCRA incinerator.

WASTEWATERS are wastes that contain less than 1% by weight total organic carbon (TOC) and less than 1% by weight total suspended solids (TSS). [See 40 CFR 268.2(f)]

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number		2. Page 1 of 1	3. Emergency Response Phone		4. Manifest Tracking Number			
							006052598 FLE			
5. Generator's Name and Mailing Address								Generator's Site Address (if different than mailing address)		
Generator's Phone:										
6. Transporter 1 Company Name								U.S. EPA ID Number		
7. Transporter 2 Company Name								U.S. EPA ID Number		
8. Designated Facility Name and Site Address								U.S. EPA ID Number		
Facility's Phone:										
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit WL/Vol.	13. Waste Codes
						No.	Type			
						01	DR	45	G	
14. Special Handling Instructions and Additional Information										
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.										
Generator's/Offor's Printed/Typed Name						Signature		Month	Day	Year
TRANSPORTER INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____									
	17. Transporter Acknowledgment of Receipt of Materials									
	Transporter 1 Printed/Typed Name					Signature		Month	Day	Year
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name					Signature		Month	Day	Year
	18. Discrepancy									
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection									
	18b. Alternate Facility (or Generator) Manifest Reference Number: _____ U.S. EPA ID Number _____									
	Facility's Phone: _____									
18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____										
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)										
1.		2.		3.		4.				
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a										
Printed/Typed Name						Signature		Month	Day	Year



PPVinc
WASTE WATER SOLUTIONS

4927 NW Front Ave.
Portland, OR 97210
Phone: (503) 261-9800
Fax: (503) 261-9900

58428 P

Plant Receiving Manifest

Certificate of Disposal

Generator	Generator Name: <u>RCE</u>		Bill to Customer					
	Location Address:		Name <u>RCE</u>					
	Mailing Address:		Address:					
	City / State / Zip: <u>Linn Co</u>		City / State / Zip:					
	Phone:		Phone:		PO#			
Waste Profile	Profile #	Waste Description		Quantity	Unit	This form to be completed by the Hauler of Nonhazardous wastes. The completed form must be presented at the disposal site prior to disposal. HAZARDOUS AND TSCA WASTE MAY NOT BE DISPOSED OF AT ANY DISPOSAL SITE. Violation of this restriction could subject you to revocation of your disposal permit. Answer all questions (please print).		
		<u>Parking lot Catch Basin</u>		<u>20,300</u>	<u>LBS</u>			
		<u>Sludge</u>						
NOTE: NON-CONFORMING WASTE MATERIALS NOT CONSISTENT WITH ESTABLISHED PROFILE MAY INCUR ADDITIONAL PROCESSING FEES.								
Transporter	Company Name / Address		I certify that the information supplied on this manifest is true, that it accurately describes the vehicle, waste and source(s) of the waste presented at the time of submission, and that the waste consists SOLELY of the non-hazardous wastes listed above to the best of my knowledge.	Disposal Site	PPV, Inc.			
	<u>RCE</u>				4927 NW Front Ave.			
	<u>11/2/13 3:00P</u>				Portland, OR 97210			
	Driver Signature	Date			Time	Analyst's Signature	Date Time	
	<u>Jos411-C</u>					<u>Jos411-C</u>		
	Print or Type Name	Date	Time		Print or Type Name	Date Time		
Screening	Microtox Toxicity Screening Results			PPV Wastewater Centrifuge Sampling				
	Sample No.:	Waste Subcategory:		Waste Stream	Time Collected	Oil Phase	Liquid Phase	Sludge / Solids
	PCB: <u>NO</u>	A (B) C Non-Reg		<u>IND</u>	<u>3:00P</u>	<u>—</u>	<u>90%</u>	<u>10%</u>
	PH: <u>7</u>							
	Pass? <u>Yes</u>	Reason for Rejection:		Comments				
Truck Information								
Capacity (gallons)								
Truck License No:								

SECTION III. CALIFORNIA LIST WASTES

COLUMN 1: LINE ITEM SEE MANIFEST	COLUMN 2: WASTE CODE / SUBCATEGORY	COLUMN 3: WASTEWATER/ NON-WASTEWATER	COLUMN 4: HANDLING CODE
	Hazardous waste containing one or more of the following <input type="checkbox"/> WW <input type="checkbox"/> Non-WW California List constituents:		1 2 3 4 5
	<input type="checkbox"/> ALL CALIFORNIA LIST CONSTITUENTS		
	<input type="checkbox"/> Liquids with nickel greater than or equal to 134 mg/l		
	<input type="checkbox"/> Liquids with thallium greater than or equal to 130 mg/l		
	<input type="checkbox"/> Liquids with PCB's > or = 50 ppm		
	<input type="checkbox"/> Waste containing HOC's > or = 1,000 mg/kg		

SECTION IV. OTHER LISTED WASTES (F006-12, F019-F028, F037-38, F039, K-, U-, AND P-CODES)

COLUMN 1: LINE ITEM SEE MANIFEST	COLUMN 2: WASTE CODE / SUBCATEGORY	COLUMN 3: WASTEWATER/ NON-WASTEWATER	COLUMN 4: HANDLING CODE
1	U009	<input type="checkbox"/> WW <input checked="" type="checkbox"/> Non-WW	3 4 5 6
2	U023, U159, U028, U154	<input type="checkbox"/> WW <input checked="" type="checkbox"/> Non-WW	3 4 5 6
5	U123	<input type="checkbox"/> WW <input checked="" type="checkbox"/> Non-WW	3 4 5 6
8	U007	<input type="checkbox"/> WW <input checked="" type="checkbox"/> Non-WW	3 4 5 6
		<input type="checkbox"/> WW <input type="checkbox"/> Non-WW	3 4 5 6

- ☐ CHECK HERE IF ADDITIONAL LISTED WASTE CODES ARE PRESENT. COMPLETE AND ATTACH LDR-1 CONTINUATION SHEET.
- ☐ CHECK HERE IF WASTE CODE F039 (MULTISOURCE LEACHATE) IS PRESENT. IDENTIFY F039 CONSTITUENTS BY COMPLETING SECTIONS II AND IV OF CHI FORM LDR-1 ADDENDUM AND ATTACH COMPLETED ADDENDUM TO THIS FORM.

SECTION V. CONTACT NAME AND DATE

Print Name: Ben Murray Date: 12-15-13

KEY TERMS/DEFINITIONS

CLASS 1 SDWA SYSTEM means a Class 1 deep well facility regulated under the Safe Drinking Water Act (SDWA).

CWA SYSTEM means a centralized wastewater treatment facility discharging under a Clean Water Act (CWA) permit. For example, a CWA facility would treat organic or inorganic aqueous wastes and discharge the treated effluent to the local sewer system. Examples of CWA treatment systems owned and operated by Clean Harbors include the wastewater treatment operations at Baltimore (including the CES system), Bristol, Chicago, Cincinnati and Cleveland.

CWA-EQUIVALENT SYSTEM means a "zero discharge system" that engages in "CWA-equivalent" treatment before land disposal. Zero-discharge facilities treat hazardous wastes using "CWA-equivalent" treatment methods, but do not discharge the treatment effluent to a sewer or water body (e.g., spray irrigation land farm). "CWA-equivalent" treatment methods means biological treatment for organics, alkaline chlorination, or ferrous sulfate precipitation for cyanide, precipitation/ sedimentation for metals, reduction of hexavalent chromium, or other treatment technology that can be demonstrated to perform equally or greater than these technologies.

HIGH TOC IGNITABLE LIQUIDS SUBCATEGORY means an ignitable liquid hazardous waste (waste code D001) which contains greater than or equal to 10% total organic carbon (TOC). Pursuant to 40 CFR 268.40, such wastes must be treated using organic recovery (RORGs) or combustion (CMBST) technology. Examples of RORGs technologies include the CES unit at Clean Harbors of Baltimore. Examples of CMBST technologies include hazardous waste fuel blending and subsequent reuse at a cement kiln, or destruction at a RCRA incinerator.

WASTEWATERS are wastes that contain less than 1% by weight total organic carbon (TOC) and less than 1% by weight total suspended solids (TSS). [See 40 CFR 268.2(f)]

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. OR D95C954314		Manifest Document No. 15711	2. Page 1 1 of 1
3. Generator's Name and Mailing Address Perimeter Technologies Inc. 140 Queen Anne St Albany, CA 97322					
4. Generator's Phone ()					
5. Transporter 1 Company Name Wash Express		6. US EPA ID Number KRG000023150		A. State Transporter's ID SSV002	
7. Transporter 2 Company Name		8. US EPA ID Number		B. Transporter 1 Phone (531) 224-3206	
9. Designated Facility Name and Site Address TRM 11618 N Lombard St. Portland, OR 97203		10. US EPA ID Number KRG000000013		C. State Transporter's ID	
				D. Transporter 2 Phone	
				E. State Facility's ID	
				F. Facility's Phone (503) 224-3206	
11. WASTE DESCRIPTION			12. Containers	13. Total Quantity	14. Unit Wt./Vol.
a.			No.	Type	
b.					
c.					
d.					
G. Additional Descriptions for Materials Listed Above			H. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.					
Printed/Typed Name			Signature		Date Month Day Year
17. Transporter 1 Acknowledgement of Receipt of Materials			Date		
Printed/Typed Name			Signature		Month Day Year
18. Transporter 2 Acknowledgement of Receipt of Materials			Date		
Printed/Typed Name			Signature		Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator; Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.					
Printed/Typed Name			Signature		Date Month Day Year

3

3

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number CRD 954314	2. Page 1 of	3. Emergency Response Phone (500) 433-3719	4. Manifest Tracking Number 005039344 FLE	
5. Generator's Name and Mailing Address 155 B Ave Ste 222 Lula Oswego, Or 97034		Generator's Site Address (if different than mailing address) 140 Queen Ave SW Albany, Or 97322				
Generator's Phone: (503) 224-3206						
6. Transporter 1 Company Name Lead Xpress		U.S. EPA ID Number CRQ C00003150				
7. Transporter 2 Company Name		U.S. EPA ID Number				
8. Designated Facility Name and Site Address 11600 N. Apts Rd. Arden, UT 84029		U.S. EPA ID Number UTD 951552177				
Facility's Phone: (435) 351-5100						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	1. IN3204, White Corrosive Liquid, Basic, Inorganic, N.O.S., (Sodium Hydroxide), 5, PG II ERG 154		02	DF	100	G
	2. IN3204, White Corrosive Liquid, Basic, Inorganic, N.O.S., (Sodium Hydroxide), 5, PG II ERG 154		01	DF	20	G
	3. IN3204, White Corrosive Liquid, Acidic, Inorganic, N.O.S., (Sulfuric Acid, Phosphoric Acid), 5, PG II ERG 154		01	DF	35	G
X	4. UN1993, Waste Flammable Liquids, N.O.S., (Methanol, Ethanol), 3, PG II ERG 124		01	DM	20	G
13. Waste Codes D002 D002 D002 D001 H002 U054 U200 H054						
14. Special Handling Instructions and Additional Information CHT 2522 755DF CHT 2522 755DF CHT 2522 755DF CHT 2522 755DF						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name		Signature			Month	Day Year
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit:			Date leaving U.S.:	
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name		Signature			Month	Day Year
Transporter 2 Printed/Typed Name		Signature			Month	Day Year
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
Manifest Reference Number:						
18b. Alternate Facility (or Generator)					U.S. EPA ID Number	
Facility's Phone:						
18c. Signature of Alternate Facility (or Generator)					Month	Day Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1.	2.	3.	4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name		Signature			Month	Day Year

